

Dougherty Ranch Granary



Structure:

- The logs are circle sawn and were milled on a water driven sawmill.
- 1 story tall
- Dovetail corners

Measurements:

- 21' (w) x 27 (l) x 11'8" (h)
- 12 courses - ~11 ½" tall
- Circle sawn

Condition:

- Sound and in good condition

History:

- Built circa 1880's
- Original location –Missoula Valley

Price:

- Please call
- Includes labeled pieces and labeled diagram for reassembly
- May include replacement pieces at the discretion of MRL.



MRL | MONTANA RECLAIMED LUMBER CO

QUALITY ANTIQUE LUMBER PRODUCTS



MRL | MONTANA RECLAIMED LUMBER CO

QUALITY ANTIQUE LUMBER PRODUCTS



MRL | MONTANA RECLAIMED LUMBER CO

QUALITY ANTIQUE LUMBER PRODUCTS

